

UNITED STATES CONS. COMMISSION IN TRIPLICATE
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐ OBSERVATION WELL	5. LEASE DESIGNATION AND SERIAL NO. NM-2512
2. NAME OF OPERATOR SHELL WESTERN E&P INC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	7. UNIT AGREEMENT NAME NORTHEAST DRINKARD UNIT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2970' FSL & 1650' FEL SEC. 3	8. FARM OR LEASE NAME NORTHEAST DRINKARD UNIT
	9. WELL NO. 210
	10. FIELD AND POOL OR WILDCAT NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 3, T21S, R37E
14. PERMIT NO. 30-025-06502	12. COUNTY OR PARISH LEA
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3479' DF	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Cmt sqzd converted to observ well</u> ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-10 to 8-31-89:

POH w/prod equip. CO to TOF @ 6738'. Wshd over fish to 6775'. Rec frac sd & scale. Mld over fish 6775'-90' & quit making hole. Did not rec any fish. Latch onto fish @ 6762', jarred & came free. Rec all of fish. Set pkr @ 6454'. Sqzd Drinkard perfs 6576' - 6760' w/100 SX Cls "C" cmt + .3% CF-1 followed by 100 SX Cls "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 6229' - 6440'. Fell free to 6590'. DO cmt to 6610'. Fell free to 6640'. DO cmt to 6770'. Pres tstd sqz to 500# for 15 min, lost 400# in 2 min. Acid perfs 6576' - 6760' w/500 gals 15% HCl. RIH w/OE tbg to 6772'. Spot 60 SX Cls "C" cmt across perfs 6576' - 6760'. Pres tstd csg to 1000# for 2 hrs, held OK. DO cmt 6445' - 6773' & fell free. Pres tstd sqz to 500#, held OK. Tagged CIBP @ 6900'. Began drlg out CIBP. Circ'd cln & POH. Tagged top of junk on BP @ 6790'. Mld on junk to 6791', could not make further progress. Fish appeared to be spinning. Decision made to leave CIBP in hole w/unknown amt & identification of metal on top. Circ'd inhib wtr. Reassembled WH & left 2-3/8" tbg hanging in well. SI well.

18. I hereby certify that the foregoing is true and correct

SIGNED J. H. SMITHERMAN

TITLE REGULATORY SUPV.

DATE 9-28-89

(This space for Federal or State office use)

APPROVED BY (CRIG. SGD.) DAVID R. GLASS
CONDITIONS OF APPROVAL, IF ANY:

DATE

*See Instructions on Reverse Side