

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOUSTON, NEW MEXICO 88400

EXPIRES AUGUST 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-2512

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

NORTHEAST DRINKARD UNIT

8. FARM OR LEASE NAME

NORTHEAST DRINKARD UNIT

9. WELL NO.

306

10. FIELD AND POOL, OR WILDCAT
NORTH EUNICE-BLINEBRY-TUBB
DRINKARD OIL & GAS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 3, T 21-S, R 37-E

12. COUNTY OR PARISH

LEA

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug-back of a well or to convert a well to a reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC. (4431 WCK)

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL & 1830' FEL SEC. 3

14. XXXXXXXX API #
30-025-06507

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3459' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

CMT SQZD

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-10 to 8-24-89:

POH w/prod equip. CO to 7050'. Set CIBP @ 5755' & PKR @ 5635'. Sqzd Blinebry Perfs 5646' - 5723' w/100 sx Cls "C" cmt + .3% CF-1 followed by 100 SX Cls "C" cmt + 2% CaCl₂. Rel PKR & POH. Tagged TOC @ 5335'. DO cmt to CIBP @ 5755'. Pres tstd sqz to 500# for 15 min, held OK. KO CIBP & pushed to 6996'. Set CIBP @ 6940'. Perf'd Blinebry/Tubb/Drinkard 5779' - 6776' (1 JSPE). Dmpd 35' cmt on top of CIBP. Acid perfs 5893' - 6776' w/7140 gals 15% HCl + 600# rock salt. Installed prod equip & ret'd to prod.

18. I hereby certify that the foregoing is true and correct

SIGNED J. H. SMITHERMAN TITLE REGULATORY SUPV.

DATE 9-28-89

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD) DAVID R. GLASS TITLE _____

DATE _____

CONDITIONS OF APPROVAL IF ANY:

OCT 18 1989

CARISBAD, NEW MEXICO *See Instructions on Reverse Side