

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Shell Oil Company</b>	8. Farm or Lease Name <b>Livingston</b>
3. Address of Operator <b>P. O. Box 1509, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>S</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>3</b> TOWNSHIP <b>21-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Drinkard</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3435 DF</b>	12. County <b>Lea</b>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Acidize w/1000 gal 15% NEA.
  - A. Clean tbg w/paraffin knife
  - B. Flow well overnight to dry tbg.
  - C. Acidize via 2" tbg w/1000 gal 15% NEA, use small pump truck.  
Flush w/lease crude.
  - D. Swab back load.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By  
SIGNED N. W. Harrison N. W. Harrison TITLE Staff Operations Engr. DATE 4-7-69

APPROVED BY [Signature] TITLE Staff Operations Engr. DATE 4-7-69

CONDITIONS OF APPROVAL, IF ANY: