

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ CAR WELL ☐ OTHER-	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC. (4431 WCK)	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001	9. Well No. 307
4. Location of Well UNIT LETTER <u>W</u> <u>660</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>3</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3433' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>Sqz, log, OAP & AT</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-26-88 to 7-6-88:

Sqz Blinebry perms 5559'-5950' and Paddock perms 5303'-5425' w/ .100 sxs class "C" cmt + .3% Halad 9 followed by 75 sxs class "C" cmt + 2% CaCl.
DO cmt to 5950'. DO thru CIBP's @ 6085' and 6150'. Set cmt ret @ 6105'. Sqz Tubb perms 6185'-6329' w/ 100 sxs class "C" cmt + .3% Halad 9 followed by 75 sxs class "C" cmt + 2% CaCl (140 sxs cmt in formation). DO cmt to 6330'. DO thru CIBP's @ 6390' and 6602', Model "D" pkr @ 6604' and CIBP @ 6615'. CO to 6674' (TD). Run GR/CNL from 6675' to 5600'. Perf Drinkard 6488'-6663' w/ 1 JSPF. Perf Blinebry 5731'-5963' w/ 1 JSPF and 6000'-6030' w/ 1 JSP2F. AT 6488'-6663' w/ 6300 gals 15% NEFE acid + 250# rock salt. AT 5930'-6030' w/ 10800 gals 15% NEFE acid + 500# rock salt. Run prod equip and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. FORE</u>	TITLE <u>SUPERVISOR REG. & PERMITTING</u>	DATE <u>OCT 19 1988</u>
Orig. Signed by <u>Paul Kautz</u> Geologist		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		