## **NEW MEXICO OIL CONSERVATION COMMISSION**

Santa Fe, New Mexico MOBIS STEPLOE GOC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checking B	below
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other) TO DUALLY COMPLETE X
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	MODOS, NEW MEXICO	May 1, 1957
Gentlemen:	(Place)	(Date)
	o do certain work as described below at the	Livingston
Shell Oil Co	on any	Well No. 2 in W
		A., Drinkerd Po
Lea	County	
(FOLL DUALLY CONTLETT:  Run Gamma Ray Collar Local Set Bridging Plug : 6400	•	REGULATIONS)
Run Gamma Ray Collar Loca Set Bridging Plug : 6400 Perforate 5 1/2" casing a 6303' - 6319'. Displace mud w/oil. Treat w/30,000 gals. gell Displace oil w/mud & drill Set Model "D" production seating nipple in stinger Displace and w/oil & swall Close elide valve, fish	ator Survey.  at w/1500 gals. MCA.  led lesse crude.  ll out bridging plug.  packer = 6500°. Run 2 1/2" tul  r. Slide valve = 6500° w/check  b in Tubb gas zons.  check valve, & swab in Drinkard	REGULATIONS)  S' - 6247', 6264' - 6292'  bing w/perforated nipple & valve below.
Run Gamma Ray Collar Loca Set Bridging Plug : 6400 Perforate 5 1/2" casing a 6303' - 6319'. Displace mud w/oil. Treat w/30,000 gals. gell Displace oil w/mud & drill Set Model "D" production seating nipple in stinger Displace and w/oil & swall Close elide valve, fish take deliverability test	ator Survey.  as follows: 6175' - 6210', 6239  at w/1500 gals. MCA.  led lease crude.  ll out bridging plug.  packer = 6500'. Run 2 1/2" tul  r. Slide valve = 6500' w/check  b in Tubb gas zons.  check valve, & swab in Drinkard  & place well on production.	regulations)  S' - 6247', 6264' - 6292'  bing w/perforated nipple & valve below.  oil zone.
Run Gamma Ray Collar Loca Set Bridging Plug : 6400 Perforate 5 1/2" casing a 6303' - 6319'. Displace mud w/oil. Treat w/30,000 gals. gell Displace oil w/mud & drill Set Model "D" production seating nipple in stinger Displace and w/oil & swall Close elide valve, fish	ator Survey.  as follows: 6175' - 6210', 6239  at w/1500 gals. MCA.  led lease crude.  ll out bridging plug.  packer = 6500'. Run 2 1/2" tul  r. Slide valve = 6500' w/check  b in Tubb gas zons.  check valve, & swab in Drinkard  & place well on production.	bing v/perforated nipple & valve below.  company or Operator
Run Gamma Ray Collar Loca Set Bridging Plug : 6400 Perforate 5 1/2" casing a 6303' - 6319'. Displace mud w/oil. Treat w/30,000 gals. gell Displace oil w/mud & drill Set Model "D" production seating nipple in stinger Displace and w/oil & swall Close elide valve, fish take deliverability test	ator Survey.  as follows: 6175' - 6210', 6239  at w/1500 gals. MCA.  led lesse crude.  ll out bridging plug.  packer = 6500'. Run 2 1/2" tul  r. Slide valve = 6600' w/check  b in Tubb gas zone.  check valve, & swab in Drinkard  & place well on production.  By  By  Position	regulations)  5' - 6247', 6264' - 6292'  bing v/perforated nipple & valve below.  oil zone.  hell Oil Company or Operator.  Javill 44 Calanu
Run Gamma Ray Collar Loci Set Bridging Plug : 6400 Perforate 5 1/2" casing a & 6303' - 6319'. Displace mud w/oil. Treat Treat w/30.000 gals. gel' Displace oil w/mud & dri Set Nodel "D" production seating nipple in stinge: Displace and w/oil & swal Close elide valve, fish a Take deliverability test  Approved	ator Survey.  as follows: 6175' - 6210', 6239  at w/1500 gals. MCA.  led lesse crude.  ll out bridging plug.  packer = 6500'. Run 2 1/2" tul  r. Slide valve = 6600' w/check  b in Tubb gas zone.  check valve. & swab in Drinkard  & place well on production.  By	regulations)  S' - 6247', 6264' - 6292'  bing v/perforated nipple & valve below.  oil zone.  hell Oil Company or Operator  Tevill