

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

SHELL WESTERN E&P INC.

3. Address of Operator

P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location

Unit Letter U : 660 Feet From The SOUTH Line and 330 Feet From The WEST Line

Section 3

Township 21S

Range 37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3476' DF

7. Lease Name or Unit Agreement Name

NORTHEAST DRINKARD UNIT

8. Well No.

302

9. Pool name or Wildcat
NORTH EUNICE BLINEBRY-TUBB-
DRINKARD OIL & GAS

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Cmt sqzd, OAP & Acd ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-09 to 11-30-89:

POH w/prod equip. CO to 6672'. Set CIBP @ 5740' & pkr @ 5478'. Sqzd Blinebry perfs 5638' - 5713' w/50 sx Cls "C" cmt + .3% CF-1 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. Tagged TOC @ 5468'. DO cmt to 5738' stopping @ 5720' to test sqz to 300#, held OK. KO CIBP & pushed to btm. Perf'd Blinebry/Tubb/Drinkard 5812' - 6646' (2 JSPP). Acd perfs 5812' - 6646' w/7350 gals 15% HCl + 750# rock salt. w/RBP set @ 5800' & pkr @ 5750', attemptd to load backside. Would not pres up. Rel pkr & retrieved RBP. Reset RBP @ 5750' & pkr @ 5625'. Pres testd backside to 500#, held OK. Estab inj rt thru prev sqzd Blinebry perfs. Set CIBP @ 5740' & pkr @ 5475'. Sqzd Blinebry perfs 5638' - 5713' w/50 sx Cls "C" cmt + .3% CF-1 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. DO cmt 5476' - 5740'. Pres testd csq (CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE

1-08-90

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 870-3797

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

JAN 12 1990

CONDITIONS OF APPROVAL, IF ANY:

to 500# for 15 min, held OK. Dried on CIRP & fell free. Pushed CIRP to
btm @ 6663'. (note: 1 cone from bit left in btm of well w/CIRP remains.)
Inst prod equip & ret'd to prod.

RECEIVED

JAN 11 1990

OCB
NOBBS C. 111

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 302
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter <u>U</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>3</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3476' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: <u>Cmt Sqz, OAP & Acdz</u> ☒		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to PBTD (6659').
3. Set CIBP @ 5740' & pkr 5570'.
4. Sqz Blinebry perms 5638' - 5713' w/50 sx Cls "C" cmt + .3% CF-1 followed by 25 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH.
5. DO cmt to 5740'. Pres test sqz to 300#. Cont drlg thru CIBP & push to btm.
6. Perf Blinebry/Tubb/Drinkard 5812' - 6646' (2 JSPF).
7. Acdz perms 5762' - 6658' w/8820 gals 15% NEFE HCl + 500# rock salt.
8. Install prod equip & ret to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 11-6-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 9 1989