

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06519

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

NORTHEAST DRINKARD UNIT

8. Well No.

207

9. Pool name or Wildcat
NORTH EUNICE BLINEBRY-TUBB-
DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

SHELL WESTERN E&P INC.

3. Address of Operator

P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location

Unit Letter P 11 : 2970 Feet From The SOUTH Line and 2308 Feet From The WEST Line

Section 3

Township 21S

Range 37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3469' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Cmt Sqzd, CO, OAP & Acd ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-07 to 10-03-89:

POH w/prod equip. CO to top of junk & fill @ 6720'. Set CIBP @ 5740' & pkr @ 5555'. Sqzd Blinbry perms 5655' - 5725' w/50 sx Cls "C" cmt + 2% CaCl₂ followed by 50 sx Cls "C" cmt + .3% CF-1 & 50 SX Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. DO cmt 5558' - 5700'. Pres tstd sqz to 500# for 15 min, held. Cont drlg cmt to 5740'. Tagged CIBP. Pres tstd csg to 500# for 15 min, held. Drld on CIBP & pushed to 6640'. CO fill & junk to 6925'. Set CIBP @ 6920'. Perf'd Blinbry/Tubb/Drinkard 5855' - 6813' (1 JSPF & 1 JSP2F). Capped CIBP w/35' cmt. Acd perms 6097' - 6813' w/25,200 gals 15% NEFE HCl + 1750# rock salt. Could not load backside w/pkr set @ 5740'. (Unable to acdz perms 5752' - 5890'.) POH w/pkr. Set CIBP @ 5805' & CIBP @ 5600'. Sqzd Blinbry perms 5655' - 5790' w/100 sx Cls "C" cmt + .2% CF-1 followed by 100 SX Cls "C" Negt cmt. Tagged CIBP @ 5538'. DO CIBP & cmt to CIBP. Pres tstd sqz to 500# for 15 min, held. KO CIBP & pushed to btm @ 6885'. Installed prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE

11-3-89

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 870-3797

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 9 1989