

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator SHELL OIL COMPANY 3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001 4. Location of Well UNIT LETTER M 3300 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 3 TOWNSHIP 21-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3434' GL, 3443' DF	7. Unit Agreement Name 8. Farm or Lease Name LIVINGSTON 9. Well No. 11 10. Field and Pool, or Wildcat TUBB OIL AND GAS 12. County LEA
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ABANDON BLINEBRY AND DRINKARD ZONES ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Pump 13 sx 75/25 poz mix cmt down DP in Drinkard string to 6520'. Pump 14 sx 75/25 poz mix down DP in Blinebry string to 5620'. WOC 24 hrs.
- Spot second plug, 5 sx 75/25 poz mix over Drinkard zone. Spot third plug, 5 sx poz over San Andres. Spot fourth plug, 5 sx poz over Queen zone. Spot fifth plug, 5 sx poz over Yates zone. Spot sixth plug, 5 sx poz over salt section. WOC 24 hrs. Pressure test squeeze to 5000 psi. Cap tubing w/10' plug.
- Spot second plug in Blinebry string over San Andres w/5 sx poz. Spot third plug over Queen zone w/5 sx poz. Spot fourth plug over Yates w/5 sx poz. Spot fifth plug over salt section w/5 sx poz. WOC 24 hrs. Pressure test squeeze to 5000 psi. Cap tbg w/10' plug.
- Return Tubb zone back to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE FEBRUARY 2, 1983

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 7 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 4 1983
HOBBS 1270