Form 9-331 Dec. 1973

Form Approved. Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY** 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME LOCKhart B-1 gas well 🗹 well other 9. WELL NO. 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME CONOCO INC. Hare Simpson 11. SEC., T., R., M., OR BLK. AND SURVEY OR 3. ADDRESS OF OPERATOR P.O. Box 460, Hobbs, N.M. 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Sec. 12 T-215 R-37F AT SURFACE: 1650 FNL & 941 FNL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: Lea AT TOTAL DEPTH: L 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL Report results of multiple completion or zone 1983 change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES OIL & CAS ABANDON* MINERALS MGMT. SERVICE (other) Clean out ROSWELL, NEW MEXICO 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* MIRU 12-14-82. RIH Whydrostatic bailer. Tagged fill @ 7980: CO to 8029. Landed the WMA@ 8000; SN @ 7970, & the anchor @ 7497! Tested they to 5000# above slips. Hang well on. Rigged down. Tested 1-3-83:2180.0BW, 36MCF in 24 hrs. Set @ Subsurface Safety Valve: Manu. and Type ... 18. I hereby certify that the foregoing is true and correct TITLE Administrative Supervisor SIGNED WM (A / Suller DATE _ (This space for Federal or State office use) PETER W. CHESTER DATE APPROVED BY CONDITIONS OF APPROVALED AND 1983