

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator SHELL WESTERN E&P INC.	8. Form or Lease Name PLUMLEE
3. Address of Operator P.O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 12 TOWNSHIP 21-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Widest WANTZ ABO
15. Elevation (Show whether DF, RT, GR, etc.) 3454' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING DEVS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER PB W/HYDROMITE; ACID FRAC ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Pull prod equip.
2. Tag PBTD ($\pm 7270'$) w/dump bailer.
3. Cap PBTD w/hydromite to 7230'.
4. Set pkr @ $\pm 6850'$.
5. Run base GR/temp survey from new PBTD ($\pm 7230'$) to $\pm 6850'$.
6. Acid frac Wantz Abo w/30,000 gals 28% HCl + 15,000 gals viscous fluid w/ $\frac{1}{2}$ ppg 100 mesh sand + 17,500 gals viscous fluid w/1 ppg 100 mesh sand + 10,000 gals non-viscous fluid.
7. SI well minimum of 48 hrs.
8. Run GR/temp survey from 6900' - PBTD 6 to 18 hrs following treatment.
9. Open well and flow thru 8/64" choke until it dies completely.
10. Release pkr & POH.
11. Install prod equip and return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. C. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 16, 1987

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE JAN 21 1987

RECEIVED
JAN 20 1987
OCD
HOBBS OFFICE