

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. box 450, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL + 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
LC-032096 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
NMFU

8. FARM OR LEASE NAME
LOCKHART B-13A

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
WANTZ ABO

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC. 13, T21S, R37E

12. COUNTY OR PARISH
LEA

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ ☐

FRACTURE TREAT ☐ ☐

SHOOT OR ACIDIZE ☐ ☒

REPAIR WELL ☐ ☐

PULL OR ALTER CASING ☐ ☐

MULTIPLE COMPLETE ☐ ☐

CHANGE ZONES ☐ ☒

ABANDON* ☐ ☐

(other) ☐ ☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU 1/29/84. SET PKR @ 5507'. SQUEEZED PERFS 5654'- 5840' w/ 200 sxs CLASS "H" w/ 27% CaCl₂. REL PKR. TOC @ 5507'. DO CMT TO 5880'. DO CIBP @ 6007'. SET PKR @ 5883'. SQUEEZED PERFS 6050'- 6300' w/ 150 sxs CLASS "H". REL PKR. TOC @ 5955'. DO CMT TO 6303'.

(ATTACHMENT)

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 5/7/84

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL MAY 10 1984

Carlsbad NEW MEXICO

*See Instructions on Reverse Side

47

RECEIVED

MAY 14 1984

O.C.D.
HOBBS OFFICE

LOCKHART B-13A #1

DO CIBP @ 6569' + CMT RETAINER @ 7025'.
DO TO 7206'. RAN LOGS. PERF W/ 2 JSPF
@ 7160'-64', 72'-78', 84'-88', 7200'-06' (48 PERFS).
SET RBP @ 7300'. PERF W/ 2 JSPF @ 7063',
72', 81', 91', 7103', 10', + 15' (14 PERFS). SET PKR
@ 6942'. ACIDIZED W/ 300 BBLS 28% HCL-NE-
FE, 20 BBLS 10 PPG BRINE, + 400 LBS ROCKSALT.
FLUSHED W/ 60 BBLS 9 PPG BRINE. SWBD. REL
PKR. RESET RBP @ 7051'. PERF W/ 2 JSPF
@ 6951', 53', 75', 78', 80', 82', 7002', 06', 13', 18', 27',
+ 7028 (24 PERFS). SET PKR @ 6788'. ACIDIZED
W/ 48 BBLS 28% HCL-NE-FE. FLUSHED W/ 60 BBLS
9 PPG BRINE. REL PKR. RESET RBP @ 6941'.
SPOTTED 4 BBLS 28% ACID 6817'-6920'. PERF
W/ 2 JSPF @ 6858', 68', 72', 81', 91', 6909', 16',
+ 6920' (16 PERFS). SET PKR @ 6725'. ACIDIZED
W/ 32 BBLS 28% HCL-NE-FE. SWBD. REL
PKR + RBP. RAN PROD EQUIP. PMPD 21
BD, 5 BW, + 25 MCF IN 24 HRS 3/9/84.

RECEIVED

MAY 14 1984

O.C.D.
NOBBS OFFICE