
Form 9-331a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	1.03	Cruces	
	1.0 ()32096	b
Unit	MAR		

SUNDRY NOTICES AT	ND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
Notice of Intention to Just Complete (INDICATE ABOVE BY CHECK MARK N	NATURE OF REPORT, NOTICE, OR OTHER DATA)
Lockhart 5-13 "A"	S line and ft. from W line of sec. 13
Mant's Abo	Range) (Meridian) Subdivision) (State or Territory) el isft.
State names of and expected depths to objective sands; show size ing points, and all of Permission is requested to Blinsbry for oil, and the Tubb casent retainer at 7020' and sewith 50 sacks. Perforate Tubb treat with seid and sandfrac to 5654-5840' with 4 jets per ft, perforations. Sun dual equipment	s, weights, and lengths of proposed casings; indicate mudding jobs, coment her important proposed work) o dually complete above well in the for gas. Completion method: set queeze off perforations 7063-7125' from 6050-6300' w/2 jets per ft, hru perforations. Perforate Blineb treat with acid and sandfree thru ent. to submitted upon completion of work
I understand that this plan of work must receive approval in v	writing by the Geological Survey before operations may be commenced.
Address 68	
sunice, New exico	By
SURICY, ROR WALVE	Title Sistrict Superintendent
	NE PERMITING OFFICE 18 9437-5