

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONVS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915) 686-6551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSWL, 1980' FWL
SEC. 13, T-21S, R-37E, UNIT LTR 'N'

5. Lease Designation and Serial No.

LC 032086B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LOCKHART B-13A # 5

9. API Well No.

30-025-06559

10. Field and Pool, or Exploratory Area

BLINERY OIL AND GAS

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-21-94 MIRU. POOH & LD 86 3/4 RODS, 133 5/8 RODS, 2 K-BARS. POOH W/TBG. RIH W/BIT & SCRAPER TO 5700'. POOH. RIH W/CIBP & SET @ 5700'. CIR & SPOT 25SX ON TOP OF CIBP 5700-5475'. PULL TBG TO 5100. SPOT 65SX FROM 5100-4485'. POOH. PERF @ 3155'. RIH W/CMT RET @ 3100'. PUMP 10SX UNDER RET @ 1000#. SPOT 20SX ON TOP FROM 3100-2910'. PERF @ 295'. SPOT 10SX DOWN 5 1/2 TO 295'. UP 7 5/8 X 10 3/4 TO SURF. CUT OFF WELLHEAD. PUT IN MARKER. FILL CELL. RIG DOWN 9-27-94

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct.

Signed

Joe G. Lara

Title

STAFF REGULATORY ASSISTANT

Date

11-5-94

(This space for Federal or State office use)

Approved by

(ORIG. SGD) JOE G. LARA

Title

PETROLEUM ENGINEER

Date

12/15/94

Conditions of approval, if any: