

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.
NO

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name NO
2. Name of Operator J. R. CONE	8. Farm or Lease Name EUBANKS
3. Address of Operator P.O. Box 10217, Lubbock, Texas 79408	9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3422 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

This Well produced from Drinkard Pool through Drinkard Perfs 6535-45 and open hole 6567-6622 from 5/49 to 3/64 End prod. 3 BOPD
GOR 7600/1, current production from Blinbry & Tubb(commingle down hole by order No 5481 & DHC-473

1. Killed well and pulled 2 1/16 tubing.
2. Remove Baker modle "D" retainer @ 6006
3. Remove Baker Modle "D" retainer @ 6420
4. Clean hole to 6622
5. Ran 2 3/8 tubing and packer to 6536 Bottom tubing and top of packer @ 6405
6. Test of Drinkard to follow

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James R Cone, Jr. TITLE Agent DATE 7/17/84
Eddie W. Sooy
APPROVED BY O. J. ... TITLE ... DATE AUG - 8 1984

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No. NO	
7. Unit Agreement Name NO	
8. Farm or Lease Name EUBANKS	
9. Well No. 2	
10. Field and Pool, or Wildcat Drinkard	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator J. R. CONE		
Address of Operator P.O. Box 10217, Lubbock, Texas 79408		
Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM West LINE, SECTION 14 TOWNSHIP 21S RANGE 37E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.) 3422 DF
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- This Well produced from Drinkard Pool through Drinkard Perfs 6535-45 and open hole 6567-6622 from 5/49 to 3/64 End prod. 3 BOPD
GOR 7600/1, current production from Blinbry & Tubb(commingle down hole by order No 5481 & DHC-473
1. Killed well and pulled 2 1/16 tubing.
2. Remove Baker modle "D" retainer @ 6006
3. Remove Baker Modle "D" retainer @ 6420
4. Clean hole to 6622
5. Ran 2 3/8 tubing and packer to 6536 Bottom tubing and top of packer @ 6405
6. Test of Drinkard to follow

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James R Cone TITLE Agent DATE 7/17/84
COPIES SIGNED BY JERRY SEXTON
SUPERVISOR DATE AUG - 2 1984