

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06593
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Northeast Drinkard Unit
8. Well No. 708W
9. Pool name or Wildcat North Eunice Blinebry-Tubb-Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐ INJECTOR ☐	
2. Name of Operator Shell Western E&P, Inc.	
3. Address of Operator P.O. Box 576, Houston, TX 77001 Attn: S.A. Galik - 5239 WCK	
4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 15 Township 21S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3425' KB	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Adjust Injection Profile ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/07 To 8/29/95

POOH w/Inj Equip. RIH w/PKR and set @ 6580'. Reset Pkr @ 6375'. Pmpd 101 BBLS 20% HCL and 500# rock salt. Rel PKR. RIH w/RBP and PKR. Set RBP @ 6037'. Test tools - held ok. Rel PKR and RBP. Reset RBP @ 5901' - Test tools - held ok. Reset PKR @ 5484'. Tst csg to 500 PSI - held ok. Pmpd 90 BBLS 20% HCL acid. Rel PKR. CO to RBP @ 5901. Reset PKR @ 5791' - no inj rate. Rel PKR and reset @ 5658'. Inj rate @ 800 PSI. Rel PKR and spot 3 BBLS 20% Acid 5826-5880. Rel PKR and reset @ 5658'. Pmpd 25 BBL 20% HCL and 800# rock salt. RIH w/CIBP and set @ 5660. Set cmt Ret @ 5421'. Pmpd 150 sxs Class C cmt. Re-sqz w/75 sx Class C into formation. Circ hole clean. TOC @ 5408'. DO CIBP & cmt to 5660'. Set cmt Ret @ 5416'. Pmp 37 Sx Class H Neat Cmt into formation. DO CIBP and CO to 6634'. Set Guiberson VI PKR @ 5404' Tsg Csg to 500# (Chart Attached). Return to Injection

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley A. Galik TITLE Mgr. Reg. & Permitting DATE 10/11/95
TYPE OR PRINT NAME For: G. S. Nady 902-4478 TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

001 24 105



