

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06594
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 711
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator SHELL WESTERN E&P INC.	
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	
4. Well Location Unit Letter P : 660 Feet From The SOUTH Line and 660 Feet From The EAST Line Section 15 Township 21S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3411' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Cmt sqzd, OAP & Acid ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-25 to 6-15-89:

POH w/prod equip. Set pkr @ 6280'. Pres tstd CIBP @ 6375' to 500# for 15 min, held OK. Reset pkr @ 5945'. Sqzd Tubb perfs 6040' - 6222' w/100 sx Cls "C" cmt + .3% CF-1 followed by 75 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. DO cmt 5917' - 6100'. Pres tstd sqz to 500#, held OK 15 min. Cont drlg cmt to 6260', fell out. Pres tstd sqz to 500#, held OK 15 min. Drl'd cmt 6370' - 77'. DO CIBP & pushed remnants to 6516'. Drl'd up CIBP remnants. Drl'd on CIBP to 6519'. Mid junk/cmt to 6548'. DO cmt to 6621'. Perf'd Blinebry/Tubb/Drinkard 5672' - 6562' (1 JSPF). Acid perfs 5672' - 6562' & Drinkard OH 6595' - 6621' w/8190 gals 15% HCl + 1000# rock salt. Installed prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE **REGULATORY SUPV.**

DATE **7-7-89**

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 870-3797

TELEPHONE NO.

(This space for State Use) **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

JUL 13 1989

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

Energy, Minerals and Natural Resources Department

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-06594</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 711
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator SHELL WESTERN E&P INC.	
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3411' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: <u>Cmt sqz, OAP & Acdz</u> ☒	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: <u></u> ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Set pkr @ 6275'. Pres tst cmt-capped CIBP @ 6375' to 500#.
3. Reset pkr @ 5950'.
4. Sqz Tubb perfs 6040' - 6222' w/100 sx Cls "C" cmt + 0.3% CF-1 followed by 25 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH.
5. DO cmt to CIBP @ 6375'. Pres tst sqz to 500#. Cont drly thru CIBP @ 6375' cmt ret @ 6518', & underlying cmt to TD (6620').
6. Perf Drinkard OH 6599' - 6618' (1 JSPF).
7. Perf Blinebry/Tubb/Drinkard 5672' - 6562' (1 JSPF).
8. Acdz Blinebry/Tubb/Drinkard w/9450 gals 15% NEFE HCl + 500# rock salt using RBP & pkr.
9. TOH w/RBP & pkr.
10. Install prod equip & ret well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE PROD. ADMIN. ADVISOR DATE 5-9-89
 TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

MAY 12 1989

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: