

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-06598</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>L.G. Warlick C</b>
8. Well No. <b>7</b>
9. Pool name or Wildcat <b>Penrose Skelly; Grayburg</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3415' KB 3429'</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
**Marathon Oil Company**

3. Address of Operator  
**P.O. Box 2490 Hobbs, NM 88240**

4. Well Location  
Unit Letter **0** : **405** Feet From The **South** Line and **2310** Feet From The **East** Line  
Section **15** Township **21-S** Range **37-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**GL 3415' KB 3429'**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <b>Recompletion</b> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/22 RU pulling unit. ND wellhead. NU BOP. RIH w/bit & scraper. Tag CIBP at 6009'. POOH. Mix & dump 4 sxs cmt on CIBP. Run GR/CCL logs from 4400' to 3600'. RIH w/CIBP, set at 4218'. RIH w/pkr, set at 3651'. Test CIBP to 1500 psi, held OK. Rel pkr. Spot 500 glas acid across Grayburg interval.

6/24 Perf 3730-40, 3745-63, 3787-3804, 3823-27. w/2 SPF. RIH w/pkr, set at 3651'. Acidize w/3000 gals 15% acid w/140 BS. Flow back well. Swab.

6/27 Rel pkr, reset at 3651'. Load & test, OK. Frac w/19,977 gals gel w/262 sxs sand. Flow back well. RIH w/sinker bars. Tag sand on CIBP at 4218'. POOH. Swab. RIH, tag sand at 4026'.

7/6 Rel pkr. POOH. RIH tag sand at 4064'. Circ hole clean. POOH. RIH w/2 3/8" tbq. ND BOP. Set TAC. NU wellhead.

7/7 RIH w/pump & rods.

7/8 RD pulling unit.

TAC at 3633' Btm of tbq 3886' SN at 3849'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 7/18/00  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY  
CLAY WINK  
RECORDS

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

7/20/00 J. H. D. C.