

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06599
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: L.G. Warlick 'C'
8. Well No. #8
9. Pool name or Wildcat Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐
2. Name of Operator **Marathon Oil Company**
3. Address of Operator **P.O. Box 2490, Hobbs, NM 88240**

4. Well Location
Unit Letter **I** : **1,650** feet from the **South** line and **990** feet from the **East** line
Section **15** Township **21-S** Range **37-E** NMPM County **Lea**
10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,416' GL; 3,427' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

07/02 - 07/03/02 Notified OCD, Buddy Hill. MIRU Triple N rig #25. POOH w/ rods.

07/08/02 NU BOP. POOH w/ production tbg. RIH w/ tubing to 6,700' and circulated hole w/ mud, pumped 25 sx C cmt @ 6,700'. WOC and tagged cmt @ 6,747'. Pumped 25 sx C cmt @ 6,700'. SDFN.

07/09/02 Notified OCD, Buddy Hill. Tagged cmt @ 6,421'. Pumped 25 sx C cmt @ 5,521'. WOC and tagged @ 5,331'. Pumped 25 sx C cmt 3,505 - 3,251'. Cut and pulled 5 1/2" casing from 2,712'. RIH w/ tbg to 2,854' and pumped 50 sx C cmt @ 2,854'. SDFN.

07/10/02 Notified OCD, Buddy Hill. Tagged cmt @ 2,568'. Pumped 30 sx C cmt 1,272 - 1,156'. Perforated casing @ 358' and squeezed 115 sx C cmt, displaced to 235'. WOC 2 hrs and tagged cmt @ 256'. Pumped 20 sx C cmt 60' to surface. RDMO.

07/11/02 Cut off wellhead and capped well, installed marker. Cut off anchors and leveled pit. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **08/02/02**

Type or print name **James F. Newman, P.E.** Triple N Services, Inc. Telephone No. **915-687-1994**

(This space for Signature of Gary W. Wink) Approved as to plugging of the Well Bore.

APPROVED BY **GARY W. WINK** Liability under bond is retained until
Conditions of approval, if any: **OC FIELD REPRESENTATIVE II/STAFF MANAGER** surface restoration is completed.

DATE **FEB 10 2003**

10/10/2020

10/10/2020