

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 06612
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9188
7. Lease Name or Unit Agreement Name	STATE S
8. Well No.	5
9. Pool Name or Wildcat	Penrose Skelly Grayburg
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459' KB	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>15</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	Recompletion <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Objective: Abandon Drinkard, Complete Penrose Skelly Grayburg

- 1) Set 5 1/2" CIBP w/35' cement cap - New PBTD=6395'
- 2) Perf 5 1/2" casing w/8 SPF 3841-51' (80 holes)
- 3) Acidize perfs w/1550 gal 15% NEFE
- 4) Ran 2 3/8" tubing w/5 1/2" packer set @ 3781'
- 5) 04/06/94: Flow 1 oil, 108 wtr, 626 MCF, 23/64" choke @ 210#.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry W. Johnson TITLE Engineering Assistant DATE 4/14/94

TYPE OR PRINT NAME Larry W. Johnson Telephone No. 397-0426

(This space for State Use)

APPROVED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE APR 18 1994

CONDITIONS OF APPROVAL, IF ANY: