

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ALBANY		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

3 - NM OCC - Hobbs
1 - File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9188	
7. Unit Agreement Name	
8. Farm or Lease Name State "S"	
9. Well No. 5	
10. Field and Pool, or Wildcat Drinkard	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Getty Oil Company

3. Address of Operator
P. O. Box 249, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER **D** , **660** FEET FROM THE **North** LINE AND **990** FEET FROM
THE **West** LINE, SECTION **15** TOWNSHIP **21-S** RANGE **37-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled out CIBP and cement at 4465'. Set CIBP at 6730' and dumped 35' cement on top. PBTD @ 6695'. Perforated Drinkard zone from 6464-6646' with 29 jets. Treated with 4500 gals. 15% NE acid, and 30,000 gals. gelled brine and 45,000# 20-40 sand, 800# salt, and 800# benzoic acid with 500 gals. 15% NE in two stages.

Released packer and laid down 3-1/2" frac tubing. Ran 2" tubing w/retrieving tool. Tagged sand at 6641'. Cleaned out sand and recovered BP. Set 2" tubing @ 6645', packer at 6450'.

Swabbing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By **C. L. WADE** TITLE **Area Supt.** DATE **5-9-75**

APPROVED BY **John Runyan** Geologist TITLE _____ DATE **MAY 1975**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY - 9 1975

GIL CONSERVATION COMM.
HOBBS, N. M.