

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06587-06813

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

Water Injector

2. Name of Operator

Shell Western E&P, Inc.

3. Address of Operator

P.O. Box 576, Houston, TX 77001 Shirley Galik - 5239 WCK

8. Well No.

6057

9. Pool name or Wildcat

NORTH EUNICE BLINEBRY-TUBB-DRINKARD

4. Well Location

Unit Letter C : 760' Feet From The North Line and 1980' Feet From The West Line

Section

15

Township

21S

Range

37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3459' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/22/95 To 5/30/95

POOH w/Inj Eqmt. RIH w/RBP and PKR. Set RBP @ 6150'. Test tools - held ok.
Reset Pkr @ 5950. Could not establish inj rate into perfs 5974-6101. Reset RBP @ 6270
and Pkr @ 6196. No inj rate into csg leak @ 6232. Reset RBP @ 6713 and Pkr @ 6450. AT
D 1-5 zones w/2436 Gal 20% HCL and rock salt. Reset RBP to 5958 and Pkr 5850. AT 5872-5938
w/1218 Gal 20% HCL and rock salt. Reset RBP @ 5866 and Pkr @ 5861. Test tool - held ok.
Reset Pkr @ 5740. AT B-3 and B-4 Perfs 5760-5842 w/1680 Gal 20% HCL and rock salt. Pmp 40
bbls acid in perfs - had communication. Rel Pkr and retrieved RBP. Set Guiberson Pkr @ 5740
and Guiberson Uni VI @ 5555. PT csg to 500 PSI for 30 min. (Chart attached).
Return Well to Injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Shirley A. Galik

TITLE

MGR - Reg. & Permitting

DATE 8-30-95

TYPE OR PRINT NAME

For: G. S. Nady

TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 7 1995

