

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 605
4. Location of Well UNIT LETTER C 760 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 15 TOWNSHIP 21S RANGE 37E N.M.P.M.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3447' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Log, OAP & Acd <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

2-23 to 2-27-88:

POH w/prod equip. Tagged btm @ 6761'. Ran GR/CNL log from 6750' to 6300'. Set RBP @ 6400'. Ran GR/CNL log from 6350' to 5500'. POH w/RBP. Perf'd Drinkard 6502'-85' & Blinebry 5760' - 6000'. Set RBP @ 6590'. Spotted 200 gals 15% HCl-NEA from 6585' to 6285'. Acd Drinkard perfs 6502'-85' w/3780 gals 15% HCl-NEA + 1050# rock salt. Reset RBP @ 6400'. Acd Blinebry perfs 5760' - 6000' w/7350 gals 15% HCl-NEA + 1450# rock salt. POH w/RBP. Installed prod equip & ret'd well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 8-02-88

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 6 1988

CONDITIONS OF APPROVAL, IF ANY: