

| | |
|---------------------------|-----|
| NUMBER OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SAN-A-11 | |
| FILE | |
| USGS | |
| LAND OFFICE | |
| TRANSPORTER | GIL |
| | GAS |
| PRODUCTION OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the school on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking: Below

| | | | | | |
|--------------------------------------|--|---|---|--------------------------------------|--|
| NOTICE OF INTENTION TO CHANGE PLANS | | NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL | | NOTICE OF INTENTION TO DRILL DEEPER | |
| NOTICE OF INTENTION TO PLUG WELL | | NOTICE OF INTENTION TO PLUG BACK | X | NOTICE OF INTENTION TO SET LINER | |
| NOTICE OF INTENTION TO SQUEEZE | | NOTICE OF INTENTION TO ACIDIZE | | NOTICE OF INTENTION TO SHOOT (Nitro) | |
| NOTICE OF INTENTION TO GUN PERFORATE | | NOTICE OF INTENTION (OTHER) | | NOTICE OF INTENTION (OTHER) | |

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICOHobbs, New Mexico
(Place)March 13, 1964
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Tidewater Oil Company

State "S"

Well No. 6 in C

(Company or Operator)

Lease

(Unit)

NE 1/4 NW 1/4 of Sec. 15, T. 21, R. 37, NMPM, Haze Simpson Pool

(40-acre Subdivision)

Lea

County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Well presently completed in the McKee zone 7435-7470'. Well has been NIO since December, 1961.

We propose to plug off present perforations and recomplete in the Drinkard Zone as follows: Pull tubing, set cast-iron bridge plug above perforations, and dump one sack cement on bridge plug. Run Gamma Ray-Neutron logs. Pick perforations from logs, and perforate Drinkard zone. Run 3-1/2" OD X-line tubing w/RTTS tool. Acidize w/1000 gals. 15% NE acid. San fracture w/30,000 gals. lease crude and 30,000# sand.

Approved....., 19.....
Except as follows:

Tidewater Oil Company

Original-Signed

By..... C. L. WADE

Position..... Area Superintendent

Send Communications regarding well to:

Approved
OIL CONSERVATION COMMISSION

By.....

Name..... C. L. Wade

Title.....

Address..... Box 249, Hobbs, New Mexico