

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

**OIL CONSERVATION DIVISION**  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

|                                           |                              |
|-------------------------------------------|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.              |                              |
| B-9188                                    |                              |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                                                                        |                                                                                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 1. CIL WELL <input checked="" type="checkbox"/> CAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                       | 7. Unit Agreement Name<br>NORTHEAST DRINKARD UNIT                                   |
| 2. Name of Operator<br>SHELL WESTERN E&P INC.                                                                                                                                                          | 8. Farm or Lease Name<br>NORTHEAST DRINKARD UNIT                                    |
| 3. Address of Operator<br>P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)                                                                                                                                  | 9. Well No.<br>601                                                                  |
| 4. Location of Well<br>UNIT LETTER <u>D</u> , <u>600</u> FEET FROM THE <u>NORTH</u> LINE AND <u>990</u> FEET FROM<br><u>WEST</u> LINE, SECTION <u>15</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M. | 10. Field and Pool, or Widened<br>NORTH EUNICE BLINEBRY-<br>TUBB-DRINKARD OIL & GAS |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3448' GR                                                                                                                                              | 12. County<br>LEA                                                                   |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO:

|                                                |                                           |
|------------------------------------------------|-------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            |

SUBSEQUENT REPORT OF:

|                                                       |                                                               |
|-------------------------------------------------------|---------------------------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>                | ALTERING CASING <input type="checkbox"/>                      |
| COMMENCE DRILLING OPERATIONS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/>                 |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/>  | OTHER <u>OAP &amp; AT</u> <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-6-88 to 7-9-88:

Ran bit and scraper to 6850'. Perf Tubb 6067' - 6087' w/ 1 JSP2F. AT 6067' - 6087' w/ 4200 gals 15% NEFE acid. Returned to production for Blinebry/Tubb test.

8-9-88 to 8-15-88:

Ran Base GR/Temp survey from 6800' to 5500'. Perf Blinebry 5746' - 5984', Tubb 6008' - 6010' and Drinkard 6454' - 6704' w/ 1 JSPF. AT 6454' - 6704' and 5746' - 5984' w/ 13,650 gals 15% HCl + 2500 # rock salt. Run Base GR/Temp survey from 6800' - 5500'. Perf Blinebry 5679' - 5716' w/ 1JSPF. AT 5679' - 5716' w/ 3150 gals 15% HCl + 250 # rock salt. Returned to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 10-13-88  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 18 1988  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 17 1988

OCD  
MOBBS OFFICE