State of New Mexico Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM: 88240 310 Old Santa Fe Trail, Room 206 30-025-06617 DISTRICT II Santa Fe, New Mexico 87503 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. B-85 Article State of the SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) State DA 1. Type of Well: WEIT X WELL | 2. Name of Operator 8. Well No. Collins & Ware, Inc. 3. Address of Operator 9. Pool name or Wildox 508 W. Wall, Suite 1200, Midland, Texas 79701 Tubb Well Location 330 Unit Letter I: 1980 Feet From The South \_ Feet From The \_East Line and 21S 37E 16 **NMPM** Lea County Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3474' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. **SUBSEQUENT REPORT OF:** NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ALTERING CASING PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **TEMPORARILY ABANDON CHANGE PLANS** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** Re-complete in Tubb X OTHER:\_ OTHER:\_\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 8/14/96 Set retainer at 5696'. Squeeze perfs 5783'-5956' with 150 sx Premium Plus followed by 100 sx Premium Plus. Squeezed 182 sx into perfs, 26 sx in casing. Tag cement at 5644'. Drilled retainer and cement to 5960'. Tag CIBP at 6608' 8/15/96 TIH with tubing open-ended to 5972'. Spot 30 sx Micro Matrix cement. Pressure to 1200 psi. Pressure dropped less than 10 psi in 15 minutes. Left pressure on well and shut down for night. 8/19/96 Tag cement at 5809'. Drill cement 5809' to 5975'. Test squeeze to 1000 psiheld for 10 minutes. Tag PBTD at 6596'. Spot 250 gals 15% HCL 6280'-6030'. Tag PBTD at 6580'. Ran DCL/GR from 6350'-5300'. 8/20/96 Perf Tubb 6046'-6276' (27 shots). Set packer at 6003'. Acidize perfs with 3000 gals 15% HCL.

(This space for State Use)

APPROVED BY DATE

State of New Mexico Form C-103 Submit 3 Copies Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM: 88240 310 Old Santa Fe Trail, Room 206 30-025-06617 Santa Fe, New Mexico 87503 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B-85 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) State DA 1. Type of Well: MET X OTHER 8. Well No. 2. Name of Operator 5 Collins & Ware, Inc. 9. Pool same or Wildox 3. Address of Operator Tubb 508 W. Wall, Suite 1200, Midland, Tx 79701 4. Well Location 1980 Feet From The 330 East Line Feet From The Line and Ibit Letter 37E 21S 16 NMPM Range Township Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3474 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING Re-complete in Tubb OTHER: OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 8/8/96 Pumped into old perfs 3528' - 62' and did not circulate. RIH and set cement retainer at 3465'. Squeezed perfs with 100 sx Premium. RIH with 4 3/4" bit. Tag retainer at 3465' and drill to TOC on CIBP at 3696'. Test 8/9/96 squeeze-held. Drill CIBP at 3720'. 8/10/96 Drill CIBP at 5313'-5315'. Tag CIBP at 5465'. 8/11/96 TIH with cement retainer and setting tool to 5286'. Squeeze Paddock perfs (5356'-5386') w/50 sx PP follwed w/25 sx Neat. 8/12/96 WOC. Tag cement retainer at 5290'. Drill to CIBP at 5457'. Test squeeze -held. Drill 8/13/96 to 5500' and start out of hole for bit change.

best of my knowledge and belief. I hereby certify that the information above is true and complete to the Prod. Supervisor TELEPHONE NO. (915) 687-3435 Dianne Sumrall TYPE OR PRINT NAME

ORIGINAL SIGNED BY SELL & LECTOM (This space for State Use) BASTRACT I SUPERVISOR

ENTE -

APPROVED BY -