

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SALE & FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-35	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State D "A"
3. Address of Operator Drawer "D" Monument, New Mexico 88265	9. Well No. 5
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 220 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 21 S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Blinbry
15. Elevation (Show whether DF, RT, GR, etc.) 3474' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled production equipment. Set aluminum bridge plug at 5450' w/2 sx. sand on top. Perforated casing in Paddock zone from 5356' to 5386' with one shot per foot. Acidized with 2000 gals. 15% NE acid. Swab tested. Non - Commercial. Set Cast iron bridge plug at 5305' w/50' cement on top. Set cast iron br. plug at 3700' with 2 sx. cement on top. Top of cement at 3688'. Perf. casing in Eumont zone from 3528' to 3562' with 2 shots per foot. Acidized perfs. with 2625 gals. 15% NE acid. Swab Tested. Non-Commercial. Pulled tubing and packer.

Closed all valves and temporarily abandoned.

Expires 10/1/75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>John Runyan</u>	TITLE <u>Superv., Admin. Services</u>	DATE <u>6-24-75</u>
Orig. Signed by John Runyan Geologist		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		