DISTRIBUTION					
SANTA FE					
FILE			N		
U.S.G.S.					
LAND OF FICE					
TRANSPORTER	OIL				
	GAS				
PRORATION OFFIC	CE .				
OPERATOR					

PR-4

EW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL		Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	X	Notice of Intention (Other)	x	Notice of Intention (Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Hobbs, New Mexico

April 2, 1963 (Date)

AM 11

Gentlemen:

Sunray DI Oil Company		
(Company or Operator) .8W	375 NMPM Drinkard-Blinebry	ut) Pool
(40-acre Subdivision)	···· ; ; ; ; ;	

Dual Completion approved by MMOOC Administrative Order MC 1280

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

- 1. MI&RU double drum pulling unit, load hole w/lse crude,
- 2. Install BOP's and pull tbg.Run LW GR-H log from PBTD up to 5000'-set Baker Model "D" pkr e 6525.Run Baker DR NLTL plug on wireline and dump 2-3 sx on top of plug. Perforate at + 5898' w/h bullsts/ft. Test tbg to 6000 psi & BOP to 2000. Set FB at 5860' & squeeze to 5000 psi w/100 sx cmt. Pull tbg.
- 3. Perf at + 5777' w/4 bullets/ft. Run tbg & test to 6000 psi & BOP's to 2000 psi set FB 5745' squeese to 5000 psi w/100 sx cmt. Pull tbg.
- 4. Run 6% rock bit & drill out cmt.Tst squeeze jobs & cag to 2500 psi.Perf Blinebry zone & approx 5777' to 5898' w/4 bullets/ft. Run FB on 3% tbg & acidize perfs w/500 gal XM38. Sand frac Blinebry pers w/24,500 gal ref. oil, 73,500# sand using RBS.Tst Blinebry perfs.
- 5. Run 2-3/8" OD the for Blinebry & Drinkard prod. Nipple up tree & swab both mones in. Take packer leakage tot and potential each mone.

Sunray DX Oil Company Company or Operator By
R. E. Statton
PositionDistrict. Engineer. Send Communications regarding well to:
Name C. T. McClanshan P. O. Box 128, Hobbs, New Mexico
P _* U _* Box 120 _p Hobbs, New Mexico Address