

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06631
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-08105
7. Lease Name or Unit Agreement Name State Land "15"
8. Well No. 2
9. Pool name or Wildcat Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator John H. Hendrix Corporation
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040

4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 16 Township 21S Range 37E NMPM Lea County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <u>Return to Blinebry Producer</u> <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Drill out CIBP at 3657'.
2. Attempt to fish packer and Vann gun at 5507'.
3. DO CIBP at 5783'.
4. Squeeze Drinkard perms. 6410 - 6650'.
5. Squeeze Blinebry perms. 5613 - 5813'.
6. Squeeze Grayburg perms. 3708 - 3745'.
7. DO cement to 6370'.
8. Log & reperforate Blinebry 5613 - 5872'.
9. Acidize perms.
10. Test & return to production as a Blinebry producer.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie H. Westbrook TITLE Vice-President DATE 6/20/95
TYPE OR PRINT NAME Ronnie H. Westbrook (915) TELEPHONE NO. 684-6631

(This space for State Use)

Orig. Signed by
Paul Kantz
Geologist

APPROVED BY _____ TITLE _____ DATE JUN 22 1995
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 29 1095

**JOJO HUBBS
OFFICE**

2021 11 17