

12. Describe Proposed or Completed Operations - Cont.

6. RU B.J.Services, Load tbg w/20 bbl. 15% NEFEHCL to 5,000 psi. Drop detonator bar & fire guns. Bring acid rate up to 4-6 bpm, MXP 5000 psi. Displace & overdisplace acid w/1000 bbls 2% KCL wtr.
7. Flow & swab well back to recover load. Test well to evaluate max run ~~BHP~~ pending results. RD PR.