

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator SUN OIL COMPANY	5. State Oil & Gas Lease No. -
3. Address of Operator P. O. Box 1861, Midland, Texas 79701	7. Unit Agreement Name -
4. Location of Well UNIT LETTER P 330 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 21S RANGE 37E NMPM.	8. Farm or Lease Name State Land "15"
	9. Well No. 5
	10. Field and Pool, or Wildcat Wantz Abo
15. Elevation (Show whether DF, RT, GR, etc.) RT 3446 DF 3444	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Single Complete in Blinebry ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well TA in Wantz Abo & Blinebry Zones. Wantz Abo is depleted. Submitted to plug Wantz Abo & single complete in Blinebry by installation of pumping unit.

Move in & rig up.

Load hole. Install BOPS. Pull both strings tubing.

Run GR & JB to pkr @ 6820'. Shut off Abo perfs. @ 6878-7177'.

Set cast iron bridge plug @ 6800' w/4 sx. cement on plug.

Run 2-3/8 J-55, 8-RD tubing to 6040.89', mud anchor @ 6026', perf nipple @ 6023, S.N. @ 6021'.

Run 3/4 & 7/8" rods w/1-1/2" insert pump.

Set pumping unit to pump Blinebry. Blinebry perfs. @ 5768-5891'.

In 24 hrs. pumped 28 BO, 8 BW, 113 MCF, 3164/1.

Well P&A in Abo effective 6-17-74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration DATE 7-3-74
APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE
CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. -
7. Unit Agreement Name -
8. Farm or Lease Name State Land "15"
9. Well No. 5
10. Field and Pool, or Wildcat Wantz Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Sun Oil Company
3. Address of Operator Box 1861, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
RT 3446 DF 3444

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER Single complete in Blinebry ☒

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well TA in Wantz & Blinebry zones. Wantz Abo is depleted. Submitted to plug Abo & single complete in Blinebry by installation of pumping unit.

1. MIRU. Load U.T., L. T. and casing. Install Bops, POOH & lay down both strings 2" OD Buttress tubing.
2. Run CI Bridge Plug and set at 6800' w/4 sx. cement over plug. (Run on W. L.) Use GO International plug.
3. Pick up and run 2-3/8 EUE 8 RD tubing to 6000' ± w/mud anchor, perf, nipple & tbg. anchor.
4. Run 1-1/4" insert pump on 3/4" rods.
5. Hook up to 114 pumping unit as available from surplus.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration Clerk DATE 9-24-73

APPROVED BY W. D. LEECH TITLE Director DATE 9-24-73

CONDITIONS OF APPROVAL, IF ANY: