

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CAMPBELL & HEDRICK

3. Address and Telephone No.

P. O. BOX 401, MIDLAND, TEXAS 79702 915-684-4393

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990'FWL & 660'FSL Sect. 17 T21S R37E

5. Lease Designation and Serial No.

LC032096 (a)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LOCKHART #2

9. API Well No.

3002506641

10. Field and Pool, or Exploratory Area

BLINEBRY TUBBS DRINKARD

11. County or Parish, State

17-21-37

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

REMOVE RETRIEVABLE PACKER

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/19/91-Kill well. Nipple up BOP, Tag Bottom.

Pull tubing out of hole. Pick up retrieving tool.

Trip in hole with tubing. Did not get Baker retrievable packer.

Pull tubing. Trip in hole with drill collars and mill shoe.

Circulate hole and mill on packer at 6547'DF. Push packer down

hole. Trip out of hole. Remove drill collars and mill. Trip in hole

with retrieving tool. Pull plug out of hole. Trip in hole with

tubing to 6585, Run rods. Install pumping equipment. work

complete 2/27/91.

DHC285 amended-Blinebry, Tubbs, Drinkard

FILED FOR RECORD
Adm

MAY 07 1991

NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title for operator

Date 04/11/91

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

RECEIVED

MAY 20 1991

FOELK