


## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELL GOBES-CHACE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		*	October 19,	19.51
Well No. 2 is locat  SW/4 Sec. 17	ted 660 T-21-S	ft. from (N) line	e and 990 ft. from $\{E\}$ line of	of sec. <u>17</u>
(% Sec. and Sec. No.)  Drinkard	(Twp.)	(Range)	(Meridian)  New Mexic	9
(Field)		(County or Subdivision)	(State or Territor;	7)

The elevation of the derrick floor above sea level is ....... ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 10 joints, 291 feet of Spang 10-3/4 inch, 32.75 lbs. 8 rd. thd. Casing and Halliburton Guide shoe, and set @ 304 feet with 150 sacks sement. Circulated cement behind casing - job complete @ 5:00 PM, October 3, 1961. Found coment inside of casing @ 265 feet @ 4:00 PM October 16, 1951. Tested easing with 1000 lbs. for 1 hour - no leak. Started drilling formation @ 7:00 PM October 16, 1951.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	Dixilyn Drilling Company	******		
Address	Bex #3427		$\mathcal{I}$	
	Odessa, Texas	Ву	Mo Jania V Go-Owner Jr.	
***************************************		Title	Co-Owner Co-Owner	

\* \* 1.4 -1 And the second second second