

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Orig & 2cc: NMOCC

lcc: File

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 21 1 40 PM '67

5g. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Field or Lease Name <del>Hardy Blinbry Oil Unit</del>	
9. Well No. 3	
10. Field and Pool, or Wildcat Blinbry	
12. County Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Tidewater Oil Co.
3. Address of Operator P. O. Box 249, Hobbs, New Mexico 88240	4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM <b>West</b> THE <b>17</b> LINE, SECTION <b>22S</b> TOWNSHIP <b>37E</b> RANGE <b>37E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3499 DF	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well formerly Sohio Percy Hardy #1, a dual Blinbry gas and Drinkard oil well. Due to change in gas/oil ratio, Blinbry zone has been reclassified as an oil well. Well has Baker Model D packer set between Blinbry and Drinkard zones at 6520. 2-3/8" tubing set at 6630' w/GOT sleeve above packer. We propose to set plug in tubing below Model D packer, to plug off Drinkard zone, test tubing and plug, open GOT sleeve at 6489 to produce Blinbry zone, perforations 5662 - 5772, through tubing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By

SIGNED **C. L. WADE**

TITLE **Area Superintendent**

DATE **9-19-67**

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

