

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name W. W. Weatherly
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 21S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Penrose Skelly Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3471 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Dual completion work <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-1-71 Swab test. Prepare to frac.
4-2-71 Set packer and test bridge plug & casing below perfs; test OK. Displaced hole with jelled brine. Pull tubing & frac perfs 3694-3765 with 25,200 gals. gel brine & 44,000# sand.
4-3-71 Installed dual wellhead equipment.
4-4-71 Circulate to clean hole. Ran Model "D" packer with expendible plug and set @ 6550. Prepare to run tubing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Proration Clerk DATE April 5, 1971

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT 1 DATE APR 7 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 01971

OIL CONSERVATION COMM.
HOBBS, N. M.