

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Company		8. Farm or Lease Name W.W. Weatherly
3. Address of Operator P.O. Box 1861 Midland, Texas 79702		9. Well No. 4
4. Location of Well UNIT LETTER <u>K</u> <u>2052.6</u> FEET FROM THE <u>West</u> LINE AND <u>2057.6</u> FEET FROM THE <u>South</u> LINE, SECTION <u>17</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Sqz. Blinebry Perfs. Add Drinkard</u> <input checked="" type="checkbox"/>
		Perfs Acidiz. & Frac.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6/15/85 MIRU Ram WS POH w/rods & pump. TOH w/2-3/8" tbg. TIH w/4-3/4" bit & 5-1/2" csg scraper on 2-7/8" WS to 5320'
- 6/18/85 FIH w bit & scraper, CIRC hole clean w 2% KCL, tagged & cleaned out SD 6154-6185, POH, RIH w 5-1/2" RDG PKR on 2-7/8" W.S. to 6092
- 6/19/85 Set pkr at 6130' test CIBP to 1500# reset pkr at 5541' EIR into Blinebry 3 BPM at 1900# Howco sqz perfs 5825-55 & 5922-48 w/100 sks Class H + tail in w/100 sks Class H neat disp. cmt to 5800'
- 6/21/85 lwr bit drlg cmt from 5753' to 5962' test sqz to 1000# OK
- 6/25/85 lwr bit tag & circ out sd from 6185 to 6190' drlg cmt to 6218' drlg CIBP from 6218-19 CO to PBSD at 6644'
- 6/26/85 FOH w/bit TIH w/5-1/2" RDG pkr on 2-7/8" WS to 6644' unable to load hole set pkr at 6505' press annulus to 500# HOWCO acidize Drinkard perfs 6590'-6644' w/5000 gals 15% NEFEHCL acid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DeAnn Kemp TITLE Associate Accountant DATE 8/12/85

ORIGINAL SIGNED BY EDDIE SEAY

OIL & GAS INSPECTOR

AUG 16 1985

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

M

RECEIVED
AUG 15 1985
C. J. C.
HOBBS OFFICE