

Form C-103
Page 2

W.W. Weatherby #4

- 7/2/85 Gearhart perf upper Drinkard 6490-6560 1 JSP2F 36 holes 4" csg gun 23 GC TIH w/5-1/2" RDG pkr on 2-7/8" WS to 6400'
- 7/3/85 Set pkr at 6400' press annulus to 500# Howco acidize upper Drinkard perfs 6490-6560 w/7000 gals 15% NEFE HCL acid + 54 RCNBS
- 7/4/85 Rel pkr lwr thru perfs tag PB SD at 6580' reset pkr at 6400'
- 7/6/85 RU Howco press annulus to 1000# Howco frac upper Drinkard 6490 to 6560' w/35000 gals Pur-gel 30 carrying 44,250# 20/40 sd flush w/2% KCL wtr
- 7/10/85 TIH w/5-1/2" hydrostatic bailer tag & CO sd from 6590 to 6644 PBDT POH LD 2-7/8" WS & Bailer.
- 7/12/85 FIH w/2-7/8" prod. tbg. & pumping setup TS 6480' MA 6449' Perf sub 6446' SN 6445' Bkr TAC at 6130' set w/16000# tension ND BOP NU wellhead RIH w/2-1/2x11/2x18' pump on 86 rod string spaced out
- 8-6-85 24 BLU, P, 28 BD, 17 BLW, 21 MCF, GOR 7536/1 GR 36'

REC- 100
AUG 15 1985
HOBBS