

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

FEB 15 3 26 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>		8. Farm or Lease Name <b>H. T. Mattern (NCT-C)</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico</b>		9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>J</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>21-S</b> RANGE <b>37-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Penrose Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3510 GL</b>		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>
<b>Plugged and abandoned.</b>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3800' TD. Killed well with 100 barrels of water. Ran 5-1/2" CI BP and set at 3609'. Circulated and loaded hole with mud. Spotted 10 sack cement plug on top of BP. Tested plug and casing with 500#, 30 minutes. OK. Spotted 10 sack cement plug from 55' to surface. Removed well head. Cleaned location and installed dry hole marker. Plugged and abandoned, February 12, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE **Area Production Manager**

DATE **February 14, 1966**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: