11

OTHER

State of New Mexico Energy, Minera's and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO 2040 Pacheco St. 30 025 06664 Santa Fe, NM 87505 DISTRICT II P.O. Drawer DD. Artesia, NM 88210 sIndicate Type of Lease STATE FEEX DISTRICT III 6State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A zLease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" L. G. WARLICK "A" FORM C-101) FOR SUCH PROPOSALS.) Type of Well OIL WELL GAS THER 2Name of Operator
TITAN RESOURCES I, INC «Well No. Address of Operator 500 WEST TEXAS, SUITE 500, MIDLAND, TX 79701 BLINEBRY OIL AND GAS ₄Well Location 1980 SOUTH 660 Unit Letter Feet From The **EAST** Line and Feet From The Line Section 19 37E Township LEA **NMPM** County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3448' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ANBANDONMENT 🔀 PULL OR ALTER CASING CASING TEST AND CEMENT JOB

OTHER:

Describe Proposed or Completed Operations (Clearly state all pertirent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/16/98 RU wireline; TIH w/ gauge ring to 5550'; set CIBP @ 5550', cap w/ 35' cmt; RU pump truck; pump 22 bbls mud; set CIBP @ 3300'; cap w/ 35' cmt. Pump 50 bbls down pump string@ 5 BPM @ 750 psi; last 5 bbls went on vac; RD wireline.

12/17/98 MIRU well service; PU TIH w/ 40 jts 1 1/4" tbg. Landed @ 1300': RU Halliburton; displace hole w/ mud; spot 5 sx plug cmt @ 1300'; TOOH w/ tbg; tie on pump side tbg. Pump 50 sx class C cmt 3.6 BPM on vac; SDFN

12/18/98 RU BJ Services. Pump 40 sx class C w/ 12% A10 - 2 BPM, 1000 psi SQ. RD BJ. RD well service. WOC. Cut off WH, weld cap on both strings 2 7/8" tbg. Spot 10 sx cmt plug to surface. Weld 9 5/8" cap on surface casing. Install dry hole marker. Level location. Well PA'd.

r nereby centify that the #normation	above is true and	complete to th∈ be	est of my	knowledge and helie
J'	/ // ^/	1 · · · · · · · · · · · · · · · · · · ·		omeago and zeno

Triuna Clephier SIGNATURE

TITLE Regulatory Analyst

DATE 03-15-99

TYPE OR PRINT NAME Laura Clepper

TELEPHONE NO 915/498-8662

(This space for State Use

DATE