

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) 30-025-6667 06667
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No. N/A
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS		7. Lease Name or Unit Agreement Name EUNICE COM.
4. Well Location Unit Letter K : 1980 Fee: From The SOUTH Line and Section 19 Township 21S Range 37E 1980 Feet From The WEST Line County LEA		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		9. Pool name or Wildcat EUMONT GAS

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CMT JOB <input type="checkbox"/> OTHER: PERF AND FRAC <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOH W/PROD EQUIP. TIH FRAC PENROSE PERFS 3476-3580 W/61,000 GALS
OF 50-50 X-L GEL AND CO2 AND 120,000 # OF SAND.
FLOW WELL BACK.
PERF 3356-3376 W/4" GUNS, 180 DEG PHSD, 2 JHPF, 40 HOLES.
ACDZ 3445-3278 W/300 GALS OF 15% NEFE.
FRAC QUEEN PERFS 3356-3386 W/ 10,000 GALS OF 50-50 X-L GEL, CO2 AND
18,000# OF SAND, FLOW WELL BACK.
CLEAN SAND OUT TO 3640'.
TIH W/PKR AND TBG. SET PKR AT 3314' EOT 3653.
SWB/TST PENROSE AND QUEEN PERFS 3356-3580.
RETURN TO PRODUCTION ON 12-07-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 12-10-91
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____