



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 10-032591-(c)
Unit _____

A. H. BROWN
DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF <u>RE-DRILLING OR REPAIR</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ILLEGIBLE

July 1, 1963

Well No. 5 is located 330 ft. from N line and 1050 ft. from E line of sec. 19

Section 19 (Range 1 and Sec. No. 19) (Twp. 37) (Range 1) (Section 19)

Ladock & Blinetry
(Field)

Lea Subdivision

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 2519 ft. est.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Killed well 7-09-63. Pulled both strings tubing and found leak in top sub of
a er's tubing seal assembly. Re-drilling. Killed well in. ran packer
leakage test commencing 7-09-63. Test indicates leak has been repaired.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. E. Neery

Address P.O. Box 100

Island, Texas

By [Signature]

Title Asst. Engr.