OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

July 6, 1961

J. W. Peery Box 401 Midland, Texas

Gentlemen:

As a result of the work done recently on your Hardy Well No. 5 located in Unit 0 of Section 19, T-21-S, R-37-E, it will be necessary for you to submit a Packer Leakage Test.

Yours very truly,

OIL CONSERVATION COMMISSION

Leslie A. Clements Oil & Gas Inspector

DC