

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORT FORM NO. 5 43

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY J. W. Peery P. O. Box 401, Midland, Texas
(Address)

LEASE Hardy WELL NO. 5 UNIT 0 9 19 T 21-S R 37-E
DATE WORK PERFORMED June 1-10, 1961 POOL Paddock

This is a Report of (Check appropriate boxes) ☐ Results of Test of Casing Shut-off
☐ Beginning of New Casing or Tubing ☐ Completion of Well
☐ Plugging ☒ Repair tubing leak

Detailed account of work done, nature and extent of repairs made and results obtained.

Found leak in tubing seal recepticle. Pack-off 5559 - 5572 with Otis type "G" pack-off. Run packer leakage test June 4 - 10. Test indicated tubing O. K. - no further leakage.

FILL IN BELOW FOR REMEDIAL WORK REPORTS

Original Well Data:

Driller Packer Cementer Compl Date
Tbng. Dia Tong Depth Oil String Dia Oil String Depth
Perf Interval
Open Hole Interval Producing Formation

RESULTS OF WORKOVER	BEFORE	AFTER
Date of Test		<u>6/9/1961</u>
Oil Production, bbls per day		<u>61</u>
Gas Production, Mcf per day		<u>88</u>
Water Production, bbls per day		<u>10</u>
Gas Oil Ratio, cu. ft. per bbl		<u>1443</u>
Gas Well Potential, Mcf per day		
Witnessed by <u>M. Overton</u>	<u>J. W. Peery</u>	(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge

Name Jesuit Clement
Title
Date

Name
Position Partner
Company J. W. Peery