NUMBER OF COPIES RECEIVED				(Form C-102)
UISTRIBUTION				(Revised 7/1/52)
SANTA F			1	
FILE			NEW MEXICO OIL CONSERVATION COMMISSION	
U.S.G.S.				_
LAND DEFICE			Santa Fe, New Mexico	
TRANSPORTER	OIL			
	GAS			
PROBATION OFFICE			MISCELLANEOUS NOTICES	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
OPERATOR				94 - 148 - 1 3 5

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate	Nature	đ	Notice	by	Checking	Below
----------	--------	---	--------	----	----------	-------

Notice of Intention to Change Plans		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze	x	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	X	NOTICE OF INTENTION (OTHER) Sand oil frac	x	Notice of Intention (Other)	
OIL CONSERVATION CON SANTA FE, NEW MEXICO	MISSION	Hobbs, New Mexico		October 2, 19	64

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Amerada	Petrol	eum Corp	oratio	1		J. (Randle	Well No. 1	in G
	(0	Company or Op	erator)			Lo			(Unit)
		4 of Sec	20	, T	21S	R 37E	NMPM.	Drinkard	
(40-acre Su	ibdivision)			•		,	,,		

Lea.....County.

FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Pull 2-3/8" tubing. Fill 5-1/2" casing from 6600! to 6650! with sand to blank off perforations from 6605! to 6645!. Equeese Drinkard zone perforations from 6520! to 6590! with 150 sacks cement. Drill out to 6673! (Baker BP at 6675!). Pull tbg. and run Gamma Ray Neutron log. Perforate Drinkard zone from 6661! to 6671! with 4 shots per foot. Maximum of 8 shots. Run straddle packers on 3-1/2" tbg. Set lower packer at 6650! and upper packer at 6592! with sliding sleeve between packers. Treat lower perforations (6661! to 6671!) with 500 gals. 15% NE acid and sand oil frac with 10,000 gals. refined oil and 11,250# 20-40 sand. Open sliding sleeve. Treat upper perforations (6605! to 6645!) with 500 gals. 15% NE acid and sand oil frac with 10,000 gals. refined oil & 11,250# 20-40 sand. Swab test. Pull 3-1/2" tbg. and rerun 2-3/8" tubing with packer. Resume production.

Approved, 19, 19	Amerada Petroleum Corporation
Except as follows:	By Luci Car Star
Approved DIL-CONSERVATION COMMISSION	Position District Superintendent Send Communications regarding well to:
17	Name Amerada Petroleum Corporation
`itle	Address Box 668 - Hobbs, New Mexico