CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 30-025-06689 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE L DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) DAYTON HARDY "e" 1. Type of Well: GAS WELL X WELL OTHER 8. Well No. 2. Name of Operator Marathon Oil Company 3. Address of Operator 9. Pool name or Wildcat P.O. Box 552, Midland, TX 79702 BLINEBRY/DRINKARD 4. Well Location 1980 SOUTH 1980 EAST Feet From The Unit Letter Line and Feet From The Line 20 21-S 37-E NMPM LEA Section Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL:3495 KB:3506 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: RECOMPLETE BLINEBRY & DRINKARD OTHER: . Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3-7-95 MIRU PU. POOH W/RODS & PUMP. NU BOP. POOH W/TBG. TESTED BOP. C/O TO 3869'. SQZD PERFS 3940-64 W/50SX CLASS "C" CMT. SQZD GRAYBURG PERFS 3709-3822 W/125 SX CLASS "C" CMT. DRILLED OUT CMT & RETAINER FROM 3620-3828. TESTED 3709-3822 SQZ TO 1000 PSI. TEST OK. DRILLED CMT & RETAINER 3884-3967. TESTED SQZ 3940-64 TO 1000 PSI. DRILLED OUT CIBP @ 5352. C/O TO 6671' TD. ACIDIZED OPEN HOLE SECTION W/4500 GALLONS 15% HCL. SWABBED BACK TO FRAC TANK. RAN STATIC BHP. SET RBP @ 6605'. LOADED HOLE W/2% KCL. PERFORATD DRINKARD FRAC TANK. RAN STATIC BHP. SET RBP @ 6605". LOADED HOLE W/2% KCL. PERFORATD DRINKARD 6479-6592 W/2JSP4 -116 HOLES. ACIDIZED 6479-6592 W/5500 GALLONS 15% HCL. SWABBED TO FRAC TANK. RETRIEVED RBP & RESET @ 5910". LOADED HOLE W/2% KCL. PERFED BLINEBRY 5586-90, 5600-10, 5620-35, 5648-52, 5665-80, 5774-85, 5805-10, 5815-20, 5830-35, 5858-62 W/2 JSPF. (156 HOLES). ACIDIZED BLINEBRY W/3000 GALLONS 15% HCL. FRACTURED W/50,000 GALLONS 65 QUALITY CO2 FOAM & 133,000# SAND. BLEW BACK TO FRAC TANK TO CLEAN UP. POOH W/STIMULATION STRING. C/O TO 5872". INSTALLED 2 3/8" PRODUCTION TBG. ND BOP. NU TREE. INSTALL 1 1/2" PUMP & RODS. RDMO PU. SET PUMPING UNIT TURNED WELL TO TEST BLINEBRY 4-5-95. I hereby certify that the information above is true and complete to the best of my knowledge and belief. DATE 4-19-95 TYPE OR PRINT NAME TOM M. PRICE TELEPHONE NO. 915 - 682 - 1626 (This space for State Use) ORIGINAL SIGNED BY APR 25 1995 **GARY WINK** APPROVED BY TITLE FIELD REP. II

24 Brownie Skelle ER