

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Conoco Inc.	8. Farm or Lease Name M.E. WANTZ
3. Address of Operator P. O. Box 460, Hobbs, New Mexico 88240	9. Well No. 6
4. Location of Well UNIT LETTER <u>M</u> , <u>330</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>990</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>21</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat PADDOCK
15. Elevation (Show whether DF, RT, GR, etc.)	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>PERF ADD'L PAY, STIMULATE</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU. SET RBP @ 5400'. SPOT 5 BBLs 15% HCL-NE-FE  
5087'-5297'. PERF PADDOCK w/2 JSPF @ 5142', 49', 62',  
64', 68', 72', 5209', 18', 28', 56', 66', 71', 83', + 90' (TOTAL 28 PERFS).  
SET PKR @ 5000'. ACIDIZE 5141'-5314' w/100 BBLs  
15% HCL-NE-FE, 150 LBS ROCKSALT MIXED w/3 BBLs  
10 PPG BRINE, + 5 LBS GUAR GUM. FLUSH w/35 BBLs  
2% KCL TFW. SWAB. REL PKR + RBP. RUN  
PRODUCTION EQUIPMENT. TEST.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Butterfield TITLE Administrative Supervisor DATE 10/6/83

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

RECEIVED

OCT 11 1983

G.C.D.  
MOBILE COURT