

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions on
reverse side)3*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032591 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elliott "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

DRINKARD
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T-21S, R-37E

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

DF 3441

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Well Workover

☐
☐
☐
☐
☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU and install BOP. Killed well w/40 Bbls. 2% KCl.
2. GIH w/full bore pkr. and SN on 2 3/8" tbg. Set pkr. @ 6490'.
3. Acdz. OH 6525-6620' w/3000 gals. 15% NEHC1 in 3 equal stages. POH w/tbg. and pkr.
4. Perf. Drinkard 6400-06', 6412-22', 6428-42', and 6452-74' (1JSP2F). Total 30 holes w/4" DML XXIII Csg. Gun.
5. RIH w/Baker RBP, FB pkr., and SN on 2 3/8" tbg. Set RBP @ 6502' and pkr. @ 6490'. Tested RBP to 2500 psi.
6. Reset pkr. @ 6370'. Acdz. perfs 6400-74' w/4000 gals. 15% NEHC1 & 60 RNCB.
7. Frac. perfs 6400-74' w/20,000 gals. 2% KCl & 20,000# 20/40 SD in 4 equal stages. POH w/pkr. and RBP.
8. Ran 2 3/8" tbg. TS - 6549'. Ran rods and 1 1/4" pump. Removed BOP and set P.U. POP.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jeannie Owens

TITLE

Sr. Administrative Clerk

DATE

3-4-77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 14 1977

U. S. GEOLOGICAL SURVEY

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.