

RECEIVED

MAR 2 10 50 AM '93
CARL
AREA

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC 032591-A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

John H. Hendrix Corporation

3. Address and Telephone No.

223 W. Wall, Suite 525, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FEL, Sec. 21, T21S - R37E
Lea County, NM

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Elliott "A"

9. API Well No.

2

10. Field and Pool, or Exploratory Area

Blinebry

11. County or Parish, State

Sec. 21, T21S-R37E
Lea Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Test Paddock

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-1-93 POH w/ rods & tbg. Set RBP at 6103' to T.A. Drinkard-Tubb.
2-2-93 Perf. Blinebry 5547 - 5893 and acidize w/ 2750 gals.
2-3 to 2-8-93 Test Blinebry.
2-9-93 Set RBP at 5387'.
2-10-93 Perf. Paddock 5168 - 5237' and acidize w/ 1500 gals. Swabbed 100% water - No oil show.
2-10-93 Set RBP at 5145'.
2-11-93 Perf. Paddock 5124 - 5128' and acidize with 500 gals.
2-12-93 Swab 100% water - No show of oil or gas.
2-13-93 Squeeze Paddock perfs. 5124 - 5237'.
2-14-93 to 2-18-93 Drill out cement, circ. & POH w/ RBP at 5387'.
2-19-93 RIH w/ 2-3/8" tbg. Swab Blinebry to flow.

14. I hereby certify that the foregoing is true and correct

Signed

Ronnie H. Westbrook

Title Vice-President

Date March 1, 1993

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date