

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N. M. OIL & GAS COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sun Oil Company		8. FARM OR LEASE NAME Elliott -A-	
3. ADDRESS OF OPERATOR P.O. Box 1861, Midland, TX 79702		9. WELL NO. 4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2030 FNL & 330 FEL		10. FIELD AND POOL, OR WILDCAT Blinebry	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T21S, R37E Unit H		12. COUNTY OR PARISH Lea	
13. STATE NM		14. PERMIT NO. 3948 DF	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well has been TA'd for 3 years. It has irreparable casing leak problems so it is being plugged and abandoned.

MIRU, install BOP, tag fill @5334', POH w/tbg.

RIH w/4-3/4" RB, if possible CO to 5750' and perform as follows:

a) Set CIBP on WL @5700' & dump 35' cmt on top w/dump bailer, PBTD @5665'.

b) Spot 150' cmt plug (approx. 16 sx) from 5350-5200.

If can't CO fill @5334', spot 134' cmt plug (Approx 14 sx) from 5334-5200.

Locate free pt in csg, cut & pull free pipe. Circ & load hole w/mud laden brine.

Spot 150' cmt plug (approx 43 sx): 75' below (inside) cut csg to 75' above (outside) cut csg.

Continue to spot following cmt plugs:

a) 100' cmt plug (approx 50 sx @50% excess) 4350-4250.

b) 100' cmt plug (approx 50 sx @50% excess) 3000-2900.

c) 100' cmt plug (approx 50 sx @50% excess) 200-100.

Spot 10 sx @surf, cut off surf csg 4' below GL, weld on steel plate, install permanent 4 1/2" C.P. marker w/welder run bead of (Corr. Loc. Description on 4 1/2" D.P.) RR & Clean up location.

Note: All lower plugs must be tagged after they are set to verify PBTD's. If cmt plug is insufficient, spot amount needed to comply.

Plugs verified by G. Stewart USGS.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY

TITLE

Accounting Assistant

DATE

9-10-81

TITLE

DATE

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.