

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06724
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Weatherly Lease
8. Well No. 6
9. Pool name or Wildcat Blinebry/Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Stephens & Johnson Operating Company	
3. Address of Operator P. O. Box 2249, Wichita Falls, TX 76307-2249	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>21</u> Township <u>21S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate additional Blinebry and stimulate <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-1-97 MIRU, run cutrite mill and drilled out Model D packer @ 6200'. Perforated new Blinebry zones at 6182-98', 6172-76', 6018-32', 5961-68', 5952-56', 5934-46', 5930-32', 5914-24'. POP.

4-14-97 MIRU, TOH w/rods & tbg., run RTTS packer and BP, set BP 6130' and packer at 5900', acidized perms. 5914-6077' w/3,500 gals. 15% SC acid w/2000# rock salt. Moved packer to 5411'. Frac perms. 5596-6077' w/2,100 sx 20/40 sand in 90,000 gals. gelled KCL water with 20,000# rock salt in three stages. TOH w/packer, cleaned out sand and retrieve BP, run 2 3/8" tbg. & rods. POP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Gilmore TITLE Petroleum Engineer DATE 6-4-97
TYPE OR PRINT NAME Bob Gilmore TELEPHONE NO. (940) 723-2166

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

