

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

N. B. Hunt

Address of Operator

406 N. Big Spring, Midland, Texas 79703

Location of Well

UNIT LETTER F 1980 FEET FROM THE North LINE AND 3300 FEET FROM  
THE East LINE, SECTION 21 TOWNSHIP 21S RANGE 37E N.M.P.M.

15. Elevation (Show whether DF, RT, CR, etc.)

3,466' DF

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Weatherly

9. Well No.

6

10. Field and Pool or Acreage

Drinkard Blinebry

12. County

Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER Perforate & stimulate the Blinebry & Drinkard ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 11-17-82 N. B. Hunt submitted a C-103 to work on this well. On the original C-103, the starting date was anticipated to be 12-82. However, due to some unforeseen delays, the work is now expected not to begin until 10-1-83. The following is a proposed step-by-step procedure for the workover:

- 1.) Remove both strings of tubing
- 2.) Log well with TDT, CNL, & CBL
- 3.) Perforate the Drinkard as logs indicate
- 4.) Acidize & fracture the Drinkard, flow back & test
- 5.) Perforate the Blinebry as logs indicate
- 6.) Acidize and fracture the Blinebry, flow back & test
- 7.) Place well back on production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. L. Lea

TITLE Acting District Engineer

DATE 9/9/83

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE SEP 13 1983

CONDITIONS OF APPROVAL, IF ANY: